

Significance of Fault Zones

Geotechnical Relevant Characterization of Brittle Faults

- Faults are elongated complex zones of deformation, ranging from decimeters to kilometers in magnitude
- A significant internal structure of shear and extensional fractures has developed, reflecting the geometry of the strain field and, consequently, the orientation of the principal stresses
- The brittle deformation, such as particle size reduction by crushing of grains and reorientation of grains by shearing, generates the characteristic fine-grained gouge
- Low-temperature solution transfer contributes substantially to the alteration of fault rocks, in particular of gouge, through transformation and neoformation of clay minerals

Significance of Fault Zones

Geotechnical Relevant Characterization of Brittle Faults

- The significant geotechnical feature is a substantial heterogeneity, reflected by the occurrence of more or less undeformed competent blocks which are typically surrounded by a fine-grained matrix consisting of gouge and highly fractured rocks. The matrix appears to be flowing around the blocks in an anastomosing pattern
- The mainly lozenge shaped blocks exhibit a fractal distribution of dimensions, ranging from the microscale to hundreds of meters in length. Fault structures are scale independent
- A considerable heterogeneity of the stress field may exist. Variations in the stress field might be an important cause of segmentary fault zone formation
- Groundwater conditions are also highly variable. Water pressures and flow directions may change dramatically across fault zones. A fault zone acts as aquifer, aquitard and aquiclude


Fault Morphology



North Anatolian Fault Zone, Turkey
Fault Escarpment of Active Segment, near Bolu Tunnel

Fault Morphology

Characterization



Normal Faults, La Linea Tunnel, Colombia

3G
1

Gruppe
Geotechnik
Graz ZT GMBH

Case Studies

Project Data

- Rock Fill Dam (Height 120 m)
- Headrace Tunnel (Length 19.5 m, Diameter 3.5 m)
- Penstock (Length 2.6 km)
- Gross Head 1.053 m
- Total Capacity 120 MW
- Tailrace Water Canal
- Compensation Reservoir
- Treatment Plant
- Potable Water Conduit
- Irrigation Canals

HPP Misicuni, Bolivia

Case Studies

Project History

- Construction problems (TBM excavation) of the headrace tunnel due to inadequate geotechnical characterization of fault zones
- The 19.5 km long tunnel penetrates Ordovician quartzitic sandstone and slate. Faults were only identified as individual planar elements
- As a consequence of the inadequate fault model inappropriate equipment was selected which, in combination with insufficient planning and construction shortcomings, caused unforeseen stoppages of the TBM excavation due to tunnel collapse and water inflow
- The total costs for remedial work and effective time of immobilized equipment are US\$ 3 million

HPP Misicuni, Bolivia

Case Studies

*Strike – Slip Fault, Misicuni Tunnel, Bolivia
Bocatoma Portal, Intermediate Shaft*



HPP Misicuni, Bolivia

Case Studies


HPP Misicuni, Headrace Tunnel, Calio - Portal



HPP Misicuni, Bolivia

Case Studies

*Cutter Head of Buried TBM at km 18 + 513.70
Calio Heading on May 03, 1999*



HPP Misicuni, Bolivia

Case Studies

*Excavation Ahead of the TBM Using Marciavantis,
Steel Ribs and Shotcrete*



HPP Misicuni, Bolivia

Fault Structures

- The analysis of the internal fault structure gives evidence of the displacement field during faulting and indicates the orientation of principal stresses (paleostress analyses)
- From the geotechnical point of view the differentiation of extensional and compressional faults is important


Fault Structures

Foliated **soft matrix** showing ductile and brittle **compressional** deformation features

Lenticular **stiff block** showing **extension** fractures

Quartzitic Sandstone, Devonian


Graphitic Shale, Carboniferous



Formation of Melange in an Foreland Basin Overthrust Setting, Main Tunnel, Mae Kuang Irrigation Project, N – Thailand


Fault Structures

Marble block
with calcite filled
extension
fractures
embedded in
graphitic phyllite
and foliated
quartzite




Tectonic Melange in an Alpine Thrust Setting
Semmering Motorway, Tunnel Steinhaus, Austria

Fault Structures



Typical Structure of Ophiolitic Melange in Mesoscale
Egnatia Motorway, N-Greece

Fault Structures




Significantly Anisotropic Melange (Mesoscale)
Diverse Elongate Blocks (Phacoids) in Foliated Matrix

Fault Structures

**FINE - GRAINED
INTENSELY SHEARED
GOUGE**

**LOZENGE - SHAPED
BLOCKS OF NO
DEFORMATION**



Fault Zone Model, Blocks Show Fractal Dimensions,
from the Micro – to the Megascale

RESEARCH ON “BIMROCKS“

➤ **Lindquist (1994):**

The strength and deformation properties of melange.

PhD dissertation, Univ. Calif. Berkeley

➤ **Medley (1994):**

The engineering characterization of melanges and similar Block-in-Matrix Rocks (Bimrocks).

PhD dissertation, Univ. Calif. Berkeley

Fault Structures

*RESEARCH ON “BIMROCKS”
presented by ED MEDLEY*